SERVICE REPORT #SR-1004
Date of visit: 25 June 2025
Customer: Bluefin Foods
Unit: Conveyor Motor CNV-608 (Asset ID A-6140)
Tech: S. Chen

Notes:
Customer reported pressure dropping below spec. Technician inspected the unit and found worn components. Replaced bearing (P/N BRG-19, qty 1) and pressure valve (P/N VLV-75, qty 2) and filter (P/N FLT-31, qty 2). Lubricated moving parts. Labor 3.5 hrs. Total cost $304.74. Severity: critical. Recommend follow-up inspection by 18 October 2025.