SERVICE REPORT #SR-1006
Date of visit: 1 July 2025
Customer: Northwind Cold Storage
Unit: Conveyor Motor CNV-511 (Asset ID A-9134)
Tech: M. Alvarez

Notes:
Customer reported unusual vibration at start-up. Technician inspected the unit and found worn components. Replaced filter (P/N FLT-24, qty 2). Tightened mounting bolts. Labor 6 hrs. Total cost $1,067.00. Severity: high. Recommend follow-up inspection by 31 August 2025.