SERVICE REPORT #SR-1009
Date of visit: 1 February 2025
Customer: Summit Bakeries
Unit: Conveyor Motor CNV-728 (Asset ID A-3478)
Tech: R. Patel

Notes:
Customer reported oil leak near the base. Technician inspected the unit and found worn components. Replaced drive belt (P/N BLT-36, qty 2). Cleaned condenser coils. Labor 3.5 hrs. Total cost $363.66. Severity: high. No further action needed.