SERVICE REPORT #SR-1010
Date of visit: 6 February 2025
Customer: Harbor Logistics
Unit: Compressor CMP-247 (Asset ID A-8870)
Tech: S. Chen

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced filter (P/N FLT-58, qty 1). Recalibrated pressure sensor. Lubricated moving parts. Labor 2.5 hrs. Total cost $2,140.47. Severity: high. Recommend follow-up inspection by 22 March 2025.