SERVICE REPORT #SR-1011
Date of visit: 25 June 2025
Customer: Summit Bakeries
Unit: Compressor CMP-464 (Asset ID A-5278)
Tech: S. Chen

Notes:
Customer reported overheating during peak load. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-30, qty 3) and bearing (P/N BRG-12, qty 1) and filter (P/N FLT-77, qty 2). Cleaned condenser coils. Labor 4 hrs. Total cost $2,174.71. Severity: high. No further action needed.