SERVICE REPORT #SR-1013
Date of visit: 26 June 2025
Customer: Greenfield Pharma
Unit: Boiler BLR-497 (Asset ID A-6636)
Tech: R. Patel

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-20, qty 1) and filter (P/N FLT-23, qty 1). Tightened mounting bolts. Lubricated moving parts. Labor 2.5 hrs. Total cost $2,120.24. Severity: medium. Recommend follow-up inspection by 12 October 2025.