SERVICE REPORT #SR-1014
Date of visit: 2 September 2025
Customer: Northwind Cold Storage
Unit: Chiller CHL-576 (Asset ID A-3081)
Tech: M. Alvarez

Notes:
Customer reported pressure dropping below spec. Technician inspected the unit and found worn components. Replaced bearing (P/N BRG-91, qty 2). Lubricated moving parts. Labor 1.5 hrs. Total cost $1,845.02. Severity: critical. Recommend follow-up inspection by 12 October 2025.