SERVICE REPORT #SR-1016
Date of visit: 4 May 2025
Customer: Summit Bakeries
Unit: Boiler BLR-276 (Asset ID A-4000)
Tech: R. Patel

Notes:
Customer reported overheating during peak load. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-63, qty 1) and filter (P/N FLT-17, qty 3) and bearing (P/N BRG-55, qty 2). Tightened mounting bolts. Recalibrated pressure sensor. Labor 6 hrs. Total cost $2,197.28. Severity: medium. Recommend follow-up inspection by 5 June 2025.