SERVICE REPORT #SR-1017
Date of visit: 31 August 2025
Customer: Northwind Cold Storage
Unit: Chiller CHL-727 (Asset ID A-1456)
Tech: J. Okafor

Notes:
Customer reported oil leak near the base. Technician inspected the unit and found worn components. Replaced drive belt (P/N BLT-97, qty 3) and filter (P/N FLT-77, qty 3) and capacitor (P/N CAP-71, qty 1). Tightened mounting bolts. Labor 3.5 hrs. Total cost $1,328.36. Severity: medium. Recommend follow-up inspection by 12 October 2025.