SERVICE REPORT #SR-1018
Date of visit: 7 November 2025
Customer: Harbor Logistics
Unit: Boiler BLR-785 (Asset ID A-4942)
Tech: R. Patel

Notes:
Customer reported overheating during peak load. Technician inspected the unit and found worn components. Replaced capacitor (P/N CAP-75, qty 3) and pressure valve (P/N VLV-71, qty 3) and filter (P/N FLT-41, qty 3). Tightened mounting bolts. Lubricated moving parts. Labor 1 hrs. Total cost $1,172.24. Severity: medium. Recommend follow-up inspection by 26 January 2026.