SERVICE REPORT #SR-1019
Date of visit: 4 March 2025
Customer: Greenfield Pharma
Unit: Generator GEN-823 (Asset ID A-3667)
Tech: M. Alvarez

Notes:
Customer reported overheating during peak load. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-28, qty 2). Lubricated moving parts. Labor 2.5 hrs. Total cost $344.02. Severity: medium. No further action needed.