SERVICE REPORT #SR-1020
Date of visit: 21 September 2025
Customer: Summit Bakeries
Unit: Conveyor Motor CNV-907 (Asset ID A-5840)
Tech: R. Patel

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-35, qty 2) and bearing (P/N BRG-50, qty 1). Cleaned condenser coils. Tightened mounting bolts. Labor 3.5 hrs. Total cost $1,034.74. Severity: critical. Recommend follow-up inspection by 23 October 2025.