SERVICE REPORT #SR-1021
Date of visit: 23 February 2025
Customer: Harbor Logistics
Unit: Chiller CHL-627 (Asset ID A-5237)
Tech: M. Alvarez

Notes:
Customer reported pressure dropping below spec. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-44, qty 1). Recalibrated pressure sensor. Labor 4 hrs. Total cost $2,142.02. Severity: medium. No further action needed.