SERVICE REPORT #SR-1022
Date of visit: 11 September 2025
Customer: Harbor Logistics
Unit: Boiler BLR-666 (Asset ID A-2993)
Tech: R. Patel

Notes:
Customer reported oil leak near the base. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-17, qty 3) and drive belt (P/N BLT-33, qty 2) and capacitor (P/N CAP-19, qty 2). Cleaned condenser coils. Labor 6 hrs. Total cost $278.56. Severity: high. Recommend follow-up inspection by 8 November 2025.