SERVICE REPORT #SR-1023
Date of visit: 18 May 2025
Customer: Bluefin Foods
Unit: Conveyor Motor CNV-356 (Asset ID A-3914)
Tech: S. Chen

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced capacitor (P/N CAP-40, qty 1) and drive belt (P/N BLT-30, qty 2) and pressure valve (P/N VLV-16, qty 1). Recalibrated pressure sensor. Labor 3.5 hrs. Total cost $810.11. Severity: high. Recommend follow-up inspection by 13 July 2025.