SERVICE REPORT #SR-1024
Date of visit: 8 January 2025
Customer: Summit Bakeries
Unit: Compressor CMP-415 (Asset ID A-9110)
Tech: J. Okafor

Notes:
Customer reported pressure dropping below spec. Technician inspected the unit and found worn components. Replaced filter (P/N FLT-80, qty 1). Tightened mounting bolts. Lubricated moving parts. Labor 4 hrs. Total cost $1,667.25. Severity: low. No further action needed.