SERVICE REPORT #SR-1025
Date of visit: 28 April 2025
Customer: Summit Bakeries
Unit: Chiller CHL-348 (Asset ID A-7240)
Tech: S. Chen

Notes:
Customer reported pressure dropping below spec. Technician inspected the unit and found worn components. Replaced capacitor (P/N CAP-61, qty 2) and filter (P/N FLT-16, qty 1). Cleaned condenser coils. Labor 6 hrs. Total cost $321.07. Severity: high. Recommend follow-up inspection by 4 June 2025.