SERVICE REPORT #SR-1026
Date of visit: 24 January 2025
Customer: Bluefin Foods
Unit: Generator GEN-586 (Asset ID A-1017)
Tech: J. Okafor

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced capacitor (P/N CAP-44, qty 2) and filter (P/N FLT-10, qty 2). Recalibrated pressure sensor. Lubricated moving parts. Labor 1.5 hrs. Total cost $638.52. Severity: high. Recommend follow-up inspection by 3 April 2025.