SERVICE REPORT #SR-1028
Date of visit: 11 September 2025
Customer: Summit Bakeries
Unit: Generator GEN-946 (Asset ID A-9581)
Tech: L. Novak

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-89, qty 3). Cleaned condenser coils. Labor 1.5 hrs. Total cost $2,053.08. Severity: critical. No further action needed.