SERVICE REPORT #SR-1030
Date of visit: 2 January 2025
Customer: Harbor Logistics
Unit: Generator GEN-590 (Asset ID A-8542)
Tech: J. Okafor

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced drive belt (P/N BLT-94, qty 3) and filter (P/N FLT-18, qty 3). Recalibrated pressure sensor. Cleaned condenser coils. Labor 4 hrs. Total cost $669.15. Severity: high. Recommend follow-up inspection by 27 February 2025.