Pond Environmental Measurement

29.06.2013

http://

Project managers:


Dates: 14.04.2013 - 01.07.2013

Complete: 0%
Tasks: 22
People: 0

Tasks

Vorgang	Anfang	Ende
Configuration & Change Management	14.04.13	22.04.13
Select Plattform	14.04.13	15.04.13
Prepare Plattform	15.04.13	22.04.13
Developement Environment	14.04.13	22.04.13
Select Environment	14.04.13	15.04.13
Prepare Environment	15.04.13	22.04.13
Project Management	14.04.13	06.05.13
Collect Informations about Hardware	14.04.13	27.04.13
Collect Ideas and Choose Idea	21.04.13	04.05.13
Define Idea	28.04.13	04.05.13
Plan Iterations	05.05.13	06.05.13
Requirements Analysis	05.05.13	11.05.13
Analysis and Design	12.05.13	01.06.13
Define Electronic Circuits	12.05.13	18.05.13
Define System-Architecture	19.05.13	25.05.13
Define Software-Architecture	26.05.13	01.06.13
Implementation	18.05.13	30.06.13
Implement Measuring Function	18.05.13	25.05.13
Implement Response Function in Measuring Nodes	08.06.13	30.06.13
Implement Receive Function in Collecting Node	08.06.13	30.06.13
Implement Visualization Software	17.06.13	30.06.13
Test and Bug Fixing	18.05.13	22.05.13

Gantt-Diagramm



.2013

3

Ressourcendiagramm



4