
C1 (fixed gain 40)
C2 (scheduled)
transition
(cost <4mm)
unstable
(gain 42-88%)
err mean (mm)
10^2
10^1
10^0
1
2
3
4
5
Stiffness scaling S