
LEAD
FOLLOW
WAIT
BT
PWM sent
(limit ±60)
50
0
left
right
right wheel
(mm/s)
200
100
0
target
measured
0
100
200
300
400
time (s)