

Guide Repair prices – updated 8/12/25

Check for airtightness, regulation, ring key height without dismantling instrument

Service

Strip instrument, oil body for wooden instruments, replace pads, springs and touch/bumper corks as required, reassemble checking pad seating and regulation.

Pad costs are variable dependent on the instrument, so charges will be variable.

In general, cleaning and polishing will be included, but an extra charge may be made.

Repad

As service but replace all pads.

Overhaul

Replace all pads, springs and tenon corks, then as for service.

Hourly rate for other work £30/hour

CLARINET	Eb/Bb/A	Alto	Bass		
Check/adjust	35	45	45		
Service	65	85	105		
Repad	150	195	245		Pad choice
Overhaul	210	260	330		Pad choice
Tenon cork					£20
Pads fitted (each)					£15-20
FLUTE	Student	Open hole			
Check/adjust	35	60			
Service	65	110			
Repad	150	POA			Pad choice
Overhaul	200	POA			Pad choice
Tighten foot joint					£15
Replace head cork					£20
Pads fitted (each)					£15-20
SAXOPHONE	Sop/Alto	Tenor	Baritone		
Check/adjust	45/45	50	50		
Service	120/110	135	150		
Repad	POA	POA	POA		Pad choice
Overhaul	POA	POA	POA		Pad choice
Crook cork					£20
Pads fitted (each)					£20-30
DOUBLE REEDS	Oboe	Cor	Bassoon	Contra	
Check/adjust	45	50	60	POA	
Service	105/125	135	150	POA	
Repad	POA	POA	330	POA	Pad choice
Tenon cork	20	20	25	POA	
Crook cork		20	20	20	
Pads fitted (each)					£20-30