

BMW 3-Series (92-98) & Z3 (96-98) Haynes Online Manual

17 Headlight beam alignment check

Accurate adjustment of the headlight beam is only possible using optical beam-setting equipment, and this work should therefore be carried out by a BMW dealer or service station with the necessary facilities.

Basic adjustments can be carried out in an emergency, and further details are given in Chapter 12.

© 2024 Haynes Manuals, Inc. Contact us