

BMW 3-Series (92-98) & Z3 (96-98) Haynes Online Manual

## 8 Alternator - testing and overhaul

If the alternator is thought to be suspect, it should be removed from the vehicle and taken to an auto-electrician for testing. Most auto-electricians will be able to supply and fit brushes at a reasonable cost. However, check on the cost of repairs before proceeding as it may prove more economical to obtain a new or exchange alternator.

© 2024 Haynes Manuals, Inc. Contact us