

BMW 3-Series and Z4 (99-05) Includes 2006 325ci/330ci Coupe and Convertible models Haynes Online Manual.

6 Front suspension lower arm balljoint - replacement

Front suspension lower arm balljoint replacement requires the use of a hydraulic press and several suitable spacers if it is to be carried out safely and successfully. If replacement is necessary, then the arm should be removed (see Section 5) and taken to a BMW dealer or suitably-equipped workshop.

© 2024 Haynes Manuals, Inc. Contact us