

BMW 3-Series and Z4 (99-05) Includes 2006 325ci/330ci Coupe and Convertible models Haynes Online Manual.

10 Alternator - testing and overhaul

If the alternator is thought to be suspect, it should be removed from the vehicle and taken to an automotive electrician for testing. Most automotive electricians will be able to supply and replace brushes at a reasonable cost. However, check on the cost of repairs before proceeding as it may prove more economical to obtain a new or exchange alternator.

© 2024 Haynes Manuals, Inc. Contact us