

BMW 3-Series and Z4 (99-05) Includes 2006 325ci/330ci Coupe and Convertible models Haynes Online Manual.

15 Headlight beam alignment check

- 1 Accurate adjustment of the headlight beam is only possible using optical beam-setting equipment, and this work should therefore be carried out by a BMW dealer or service station with the necessary facilities.
- 2 Basic adjustments can be carried out in an emergency, and further details are given in Chapter 12.

© 2024 Haynes Manuals, Inc. Contact us