

BMW 3-Series (92-98) & Z3 (96-98) Haynes Online Manual

## 6 Front suspension control arm balljoint - replacement

## Note:

This applies to the outer balljoint only; the center balljoint is integral with the control arm and can't be replaced separately.

Front suspension control arm balljoint replacement requires the use of a hydraulic press and several suitable spacers if it is to be carried out safely and successfully. If replacement is necessary, then the arm should be removed (Section 5) and taken to a BMW dealer or other qualified repair shop. Note: Technicians with the necessary tools can replace the balljoint without removing the arm from the vehicle.

© 2024 Haynes Manuals, Inc. Contact us