

Printer Dover

Spruce version 11.2 -- spooler version 11.2

File: ProcL-MWrev-Cg-to-Ch-rework.sil

Creation date: 17-Mar-80 16:20:05

For: Spruce

2 total sheets = 1 page, 1 copy.

Problems encountered:

Font HELVETICA24B substituted for font HELVE24.

ProcL Multiwire Rework Instructions for Rev Cg to Rev Ch

1. **Cut Chip Leg k15-10 (RBaseBypass')**

2. **Install MC102 @ location i10**

3. **Install the following blue wires**

 k15-11 to i10-7 (NextMacroDly')

 g19-9 to i10-6 (Hold)

 i10-6 to g19-2 (RBaseBypass')

 i10-1 to i10-16 (GND398)

 i19-4 to e21-12 (Curr = Next')

4. **Remark board using indelible ink to Rev Ch**

ProcL-MWrev-Cg-to-Ch-rework.sil

XEROX <i>PARC</i>	<i>Project</i> Dorado	<i>Reference</i> MW-rev-Cg to Ch Rework	<i>File</i> See Above	<i>Designer</i> Diebert	<i>Rev</i> Ch	<i>Date</i> 3/17/80	<i>Page</i> 01
-----------------------------	---------------------------------	---	---------------------------------	-----------------------------------	-------------------------	-------------------------------	--------------------------