

Printer Dover

Spruce version 11.2 -- spooler version 11.2

File: RevStatus.memo

Creation date: April 10, 1981 12:24 PM

For: Spruce

3 total sheets = 2 pages, 1 copy.

Problems encountered:

Font HELVETICA24B substituted for font HELVE24.

Inter-Office Memorandum

To	Dorado Core	Date	March 17, 1980
		Updated	April 10, 1981
From	Tim Diebert	Location	Palo Alto
Subject	Dorado Board Revisions	Organization	CSL

XEROX

Filed on: [IVY]<DoradoDocs>RevStatus.memo
[IVY]<DoradoDrawings>RevStatus.press

The following list represents what I believe to be the current board revision status information. It summarizes the current revision as well as all known null revisions of interest.

BaseBoard	Ak to Al	Null
	Al	Current
	Bb	Current for MW Stichweld boards
ContB	Cd	Current
ContA	Cd	Current
ProcL	Cf to Cg	Null
	Cg to Ch	Hold Fix
	Ch to Ci	Terminating resistors (Multiwire only. Stichweld rev is Null) Withdrawn!! use only with socketed MW boards.
ProcH	Cd to Ce	Null
	Ce	Current
IFU	Bh	Old least acceptable rev. To be scrapped
	Ce to Cf	Multiwire Layout Change
	Cf to Cg	Fix interrupts after XFER
	Cg	Current Blue Wire rework for bare Cf MW boards
	Ch	Current new bare MW board
MemC	Bd to Be	Null
	Be	Current
MemX	Cc	Old least acceptable rev. Not reworkable, however functional.
	Cg	Current
MemD	Bc to Bd	Null
	Bd to Be	Null
	Be	Current (1k cache chips)
	Ca	Current (4k cache chips)
MSA Stichweld	Bg	Current

Dorado Board Revisions

2

PCMSA	Pc	Current
DskEth	Bd	Old least acceptable rev. To be scrapped.
	Cc to Cd	Null
	Cd to Ce	Null
	Ce	Current
DispY	Cd to Ce	Needed
	Ce to Cf	Needed
	Cf to Cg	Needed
	Cg to Ch	Needed (in error) to fix color problems
	Ch to Ci	Current