

Printer Dover

Spruce version 11.2 -- spooler version 11.2

File: IFU-Cf-to-Cg-mwRW.sil

Creation date: 10-Apr-81 12:29:02

For: Spruce

2 total sheets = 1 page, 1 copy.

Problems encountered:

Font HELVETICA24B substituted for font HELVE24.

IFU mwRev Cf to Cg Rework instructions

1. Cut the following IC leg
b22-5 (Exception)
2. Install the following blue wires
i16-3 to b22-5 (IC Leg)
b22-5 to b52-8 (Exception Dispatch)
3. Remark Board as Rev Cg

[IVY]<DoradoLogic> IFU-Cf-to-Cg-mwRW.sil

XEROX <i>PARC</i>	<i>Project</i> Dorado	<i>Reference</i> IFU mwRev Cf to Cg Rework	<i>File</i> See Above	<i>Designer</i> Diebert	<i>Rev</i> Cg	<i>Date</i> 4/10/81	<i>Page</i> 01
-----------------------------	---------------------------------	--	---------------------------------	-----------------------------------	-------------------------	-------------------------------	--------------------------