AutoInspect AI

Official Vehicle Damage Assessment Report

Generated on: 3/29/2026, 10:27:44 PM

Vehicle Information

Make & Model: BMW 520d
Year: 2019
Number Plate: KL66D4156
Project ID: 69c958f9a1ba3bde28e7bf46

Incident Details

Driver Name: Aloke Saji
Driver License: DL- 2345678901
Description: "On May 10, 2024, at approximately 4:30 PM, a vehicle accident occurred on the eastbound lane of Highway 50, near the intersection with Maple Grove Road, in Springfield, State. The incident involved a silver Honda Civic, driven by Jane Doe, and a blue Ford Escape, operated by John Smith. Jane Doe was attempting to change lanes when she collided with the Ford Escape, which was in her blind spot. The impact caused significant damage to the rear passenger side of the Ford Escape and the front driver side of the Honda Civic. Both vehicles pulled over to the side of the highway immediately after the collision. Emergency services were notified and arrived at the scene within minutes. Paramedics conducted on-site evaluations of both drivers. Jane Doe reported minor whiplash but declined further medical treatment. John Smith sustained a minor cut on his forehead and was treated at the scene. Law enforcement officers conducted an initial investigation, including statements from both drivers and witnesses. Preliminary findings suggest that the Honda Civic's unsafe lane change was the primary cause of the accident. Traffic was moderately affected for approximately 45 minutes as the vehicles were moved and debris cleared from the roadway. Both vehicles were towed from the scene due to the extent of the damage. Insurance information was exchanged between the drivers, and a formal accident report was filed by the responding officer. The report will be submitted to the Department of Motor Vehicles and made available to both parties for insurance claims. Photographs of the accident scene, damage to both vehicles, and the surrounding area were taken for further analysis. The incident will undergo a more detailed investigation to finalize determinations of fault and to assess any potential charges or citations.
Witnesses: 2 people

Damage Analysis & Cost Estimation

Damaged Part	Estimated Cost (INR)

rear-bumper-dent	₹8,000 - ₹25,000
front-bumper-dent	₹8,000 - ₹25,000
quaterpanel-dent	₹15,000 - ₹40,000
fender-dent	₹7,000 - ₹22,000
Windscreen-Damage	₹20,000 - ₹45,000
doorouter-dent	₹8,000 - ₹25,000

Total Consolidation: ₹66,000 - ₹182,000

Authorized By (Digital Signature)

Alan Varghese