AutoInspect AI

Official Vehicle Damage Assessment Report

Generated on: 4/2/2026, 11:08:36 AM

Vehicle Information

Make & Model: Suzuki / Maruti Suzuki Dzire
Year: 2025
Number Plate: KL01AB1267
Project ID: 69cdff4e67c9f52bf86b7f79

Incident Details

Driver Name: Joyal James
Driver License: DL- 2345678901
Description: it happened fast
Witnesses: it was empty

Damage Analysis & Cost Estimation

Damaged Part	Estimated Cost (INR)
Taillight-Damage	₹3500 - ₹6500
doorouter-dent	₹3500 - ₹7000
front-bumper-dent	₹3500 - ₹7000
Bonnet Dent Repair	₹3500 - ₹8000

Total Consolidation: ₹14,000 - ₹28,500

Authorized By (Digital Signature)

Aloke Saji