Formulir 104-A Report SKK Migas (gaya) - Directional Survey ARUN-07

Preview A4 seperti Figma Safety Incident and Directional Survey. Seal SHA-256 valid.

Survey stations (MD, INC, AZI)

MD (m)	INC (deg)	AZI (deg)	TVD (m)
2600	1.2	045	2598
2700	1.5	048	2697
2800	1.8	050	2796
2835	1.8	051	2831

Insiden IR-2026-014: hose rupture, severity High, status Review. Corrective action 48 jam: ganti hose + briefing crew. Lampiran: IMG_20260910_HoseRupture.jpg, RigMedic_Clearance_IR14.pdf.

Superintendent	HSE Officer	Seal
(sign)	(sign)	SHA-256 valid