Control cableado

Instrucción CUA

Condición	μOperaciones	Siguiente
Ciclo de búsqueda		
t0	$PC \rightarrow MAR$	$SR+1 \rightarrow SR$
t1	$M \rightarrow GPR; PC+1 \rightarrow PC$	$SR+1 \rightarrow SR$
t2	$GPR(OP) \rightarrow OPR$	$SR+1 \rightarrow SR$
Ciclo de ejecución de CUA		
i1·t3	$SC \leftarrow 12; GPR \leftarrow 0$	$SR+1 \rightarrow SR$
i1·t4	ROL Acc; $SC \leftarrow SC - 1$	$SR+1 \rightarrow SR$
i1·t5·F	$GPR \leftarrow GPR + 1$	
i1·t5·ZSC		$SR+1 \rightarrow SR$
i1·t5·ZSC		$4 \rightarrow SR$
i1·t6	Acc ← 0	$SR+1 \rightarrow SR$
i1·t7	$Acc \leftarrow GPR + Acc$	$0 \rightarrow SR$
i1·t7·ZGPR	$PC \leftarrow GPR(AD)$	

Expresiones de control

μOperación	Expresión de control	
$PC \rightarrow MAR$	t0	
$M \rightarrow GPR$	t1 + i1·t4	
PC+1 → PC	t1	
$GPR(OP) \rightarrow OPR$	t2	
SC ← 12	i1·t3	
GPR ← 0	i1·t3	
ROL Acc	i1·t4	
$SC \leftarrow SC - 1$	i1·t4	
$GPR \leftarrow GPR + 1$	i1·t5·F	
Acc ← 0	i1·t6	
$Acc \leftarrow GPR + Acc$	i1·t7	
$PC \leftarrow GPR(AD)$	i1·t7·ZGPR	
$SR+1 \rightarrow SR$	$t0 + t1 + t2 + i1 \cdot t3 + i1 \cdot t4 + i1 \cdot t5 \cdot ZSC + i1 \cdot t6$	
Load SR	$i1 \cdot t5 \cdot \overline{ZSC} + i1 \cdot t7$	

