Harbour structures

The station was modernised in stages. A clockwork rotation mechanism replaced the hand-cranked one in 1902, an acetylene burner arrived in 1923, and electricity followed in 1951, carried across the sound on a cable that the fishermen swore would never hold.

Structure	Material	Built	Length (m)	Cost (MNOK)	Condition
North pier	Concrete	1954	212	18.4	Good
South pier	Timber	1931	148	9.7	Fair
Ferry berth	Steel	1988	96	31.2	Good
Fish market quay	Concrete	1967	175	22.9	Poor
Boatyard slip	Concrete	1972	64	4.1	Fair
Marina pontoon A	Composite	2009	120	12.6	Good
Marina pontoon B	Composite	2011	120	12.6	Good
Old customs steps	Granite	1889	22	0.8	Fair
Fuel jetty	Steel	1995	48	6.5	Good
Lifeboat ramp	Concrete	1979	38	3.3	Poor
East breakwater	Rock armour	1926	410	54.0	Fair
West breakwater	Rock armour	1926	355	47.8	Good
Total			**1808**	**223.9**	

Daily life followed the light. The lamp was trimmed at dusk and dawn, the lens polished every morning, and the brass fittings once a week whether they needed it or not. Supplies came by boat every second Thursday, weather permitting, which in February it rarely did.