# INY2 M17B

## LIMPIAR ZONA DEL MOLDE

|        | 2024L3                       |         |         |         | 0.1802 |
|--------|------------------------------|---------|---------|---------|--------|
| $\sim$ | 80.0802<br>loc face 2024 / Y | 79.0000 | 79.9000 | 78.4000 | 1.0802 |

## LIMPIAR ZONA DEL MODE

| 301   | 15SQ1                         |          |        | 0.1399  |
|-------|-------------------------------|----------|--------|---------|
|       | 1.3399                        | 0.0000   | 1.2000 | 1.3399  |
| X     | 205.5223                      | 204.8527 |        | 0.6697  |
|       | -7.3759                       | -7.3955  |        | 0.0196  |
| Z for | -23.6137<br>rme face 3015 / X | -23.6077 |        | -0.0060 |

## FALTA DE MATERIAL EN EL LAMADO , MAL CIERRE

| 3072L2                        |          |          |          | -0.0100 |
|-------------------------------|----------|----------|----------|---------|
| 182.6900<br>loc face 3072 / X | 183.3000 | 183.9000 | 182.7000 | -0.6100 |
|                               |          |          |          |         |

## NO SE PUEDE CAMBIAR EN MAQUINA

| 6031L1                           |                    |        | 0.0551            |
|----------------------------------|--------------------|--------|-------------------|
| 1.2551                           | 0.0000             | 1.2000 | 1.2551            |
| X 169.5683                       | 170.0000           |        | -0.4317           |
| Y 6.6445<br>loc 6031 / YX (8,23) | 7.1000             |        | -0.4555           |
| 6031L2                           |                    |        | 0.0900            |
|                                  |                    |        |                   |
| 1.6900                           | 0.0000             | 1.6000 | 1.6900            |
| 1.6900<br>X 169.5567             | 0.0000<br>170.0000 | 1.6000 | 1.6900<br>-0.4433 |



