
NO CONFORMIDADES MOLDE 13B


CAMBIAR PINES (3041 ENDEREZAR EN DIRECCION A LA BOMBA DE AGUA)

2042L2 loc fond 2042 / Y	119,9750	117,8000	0,9000	-0,9000	2,1750 🌑 الماليان	1,2750
CARA 300 ▶3041						
Ф 3041L4 loc 3041/ZY (19.3)	2,9627	0,0000	2,0000	0,0000	2,9627	0,9627
Ф ^{3041L4.Z}	-110,2461	-111,5000	1,0000	-1,0000	1,2539	0,2539
≥ 3041L4Z	110,2461	111,5000	1,0000	-1,0000	-1,2539 🛑 📥 🔟	-0,2539
3072L2 loc face 3072 / X	182,4472	183,3000	0,6000	-0,6000	ليليا 🛑 -0,8528 🛑	-0,2528
4104L1Z	148,3948	149,0000	0,6000	-0,6000	-0,6052 ()	-0,0052
♦ 4104L1 loc 4104 / ZX (4,98)	1,2162	0,0000	1,2000	0,0000	1,2162	0,0162
Ф ^{4104L1.Z}	-148,3948	-149,0000	0,6000	-0,6000	0,6052	0,0052
● 6070L2	190,7675	192,0000	0,9000	-0,9000	-1,2325 🔴 📥 🕕	-0,3325
loc fond 6070 / Y						

V305SQ1 LIMPIAR ZONA





LIMPIAR ZONA



LIMPIAR ZONA







Faltas material pieza:

Exceso material pieza: