

- 2. Break all sharp edges and mask all threads prior to powder coat.
- 3. Part is to be powder coated with Cardinal color C241-BK109. Thickness of coating must not exceed 0.08mm.
- 4. Ink mark in area indicated with first initial of your company name.

| Rev | Date | Description |
|-----|---------|----------------------------------------------------------------|
| Е | 2/27/16 | Countersink removed from 2 masked holes for manufacturability. |
| D | 7/6/16 | FreeCAD redraw. Masking added to countersunk holes (page 2) |
| С | 9/28/15 | Location of supplier identification stamp changed (note 4) |

