```
1 #ifndef MOTOR_H_INCLUDED
 2
   #define MOTOR_H_INCLUDED
 3
 4 #include "stm32f0xx_ll_gpio.h"
 5 #include "defs.h"
 6
 7
   #define L298_IN1_Reset() LL_GPIO_ResetOutputPin(GPIOB, LL_GPIO_PIN_7)
 8 #define L298_IN1_Set()
                                  LL_GPIO_SetOutputPin(GPIOB, LL_GPIO_PIN_7)
 9
10 #define L298_IN2_Reset() LL_GPIO_ResetOutputPin(GPIOB, LL_GPIO_PIN_8)
11 #define L298_IN2_Set() LL_GPIO_SetOutputPin(GPIOB, LL_GPIO_PIN_8)
12
13 #define L298_ENA_Reset() LL_GPIO_ResetOutputPin(GPIOB, LL_GPIO_PIN_9)
14 #define L298_ENA_Set() LL_GPIO_SetOutputPin(GPIOB, LL_GPIO_PIN_9)
15
16
                                       500
17
   #define MOTOR_SPEED_DEF
18 #define MOTOR_DELAY_TIME_DEF 3
    #define MOTOR_PAUSE_TIME_DEF 2
20
21
   void L298 Init(SysData TypeDef *self);
23
    void L298_Process(SysData_TypeDef *self);
24
   void L298_OpenWindow(SysData_TypeDef *self);
25
   void L298_CloseWindow(SysData_TypeDef *self);
27
    void L298_MotorStop(SysData_TypeDef *self);
28
29 #endif /* MOTOR_H_INCLUDED */
```