



.040

tan 67.5 = .04/Z z = 0.04/tan(67.5) = 0.016568542494924pos 6 Z = -0.5500 + 0.016... = -0.533431457505076 = -0.5334



?



X center = .95 - .010 * 2 = 0.9300 Z center = -0.8375 - 0.004142135623731 = -0.841642135623731 = -0.8416 tan 67.5 = 0.010 / Z Z = 0.010 / tan 67.5 = 0.004142135623731

