
19. Front Accessory Power Supply Socket System

A: WIRING DIAGRAM

FAPS-01





WI-34207