10.General Diagnostic Table

A: INSPECTION

1. IMPROPER VEHICLE POSTURE OR IMPROPER WHEEL ARCH HEIGHT

Possible cause	Corrective action	
(1) Permanent distortion or damaged coil spring	Replace.	
(2) Rough operation of shock absorber	Replace.	
(3) Installation of the wrong shock absorber	Replace with proper parts.	
(4) Installation of the wrong coil spring	Replace with proper parts.	

2. POOR RIDE COMFORT

- 1) Large rebound shock
- 2) Rocking of the vehicle continues too long after running over bump and hump.
- 3) Excessive shock in bumping

Possible cause	Corrective action	
(1) Damaged coil spring	Replace.	
(2) Overinflation of tires	Adjust.	
(3) Improper wheel arch height	Replace the coil springs with new parts.	
(4) Defective operation of shock absorber	Replace.	
(5) Damage or deformation of shock absorber mount	Replace.	
(6) Unsuitable length (maximum or minimum) of shock absorber	Replace with appropriate parts.	
(7) Deformation or loss of bushing	Replace.	
(8) Deformation or damage of helper in shock absorber	Replace.	
(9) Oil leakage from the shock absorber	Replace.	

3. NOISE

Possible cause	Corrective action	
(1) Wear or damage of shock absorber component parts	Replace.	
(2) Loosening of the suspension link or arm installing bolt	Tighten to the specified torque.	
(3) Deformation or loss of bushing	Replace.	
(4) Unsuitable length (maximum or minimum) of shock absorber	Replace with appropriate parts.	
(5) Damaged coil spring	Replace.	
(6) Wear or damage of the ball joint	Replace.	
(7) Deformation of the clamp - stabilizer bushing	Replace.	

WHEEL AND TIRE SYSTEM



		Page
1.	General Description	2
2.	Tire and Wheel	4
	"T-type" Tire	
	Full Wheel Cap	
	Tire Pressure Monitoring System	
	Tire Repair Kit	
	General Diagnostic Table	