36. Push Button Start System

A: WIRING DIAGRAM







