PCMSK0 – Pin Change Mask Register 0 Bit

(0x6B)

Read/Write

Initial Value

R/W

PCINT5

R/W

PCINT6

R/W

PCINT4

R/W

PCINT3

R/W

PCINT2

R/W

PCINT1

R/W

PCINT0

R/W