


















Sheet: /CONNECTORS M1/ File: connectors.kicad_sch		
Title: POWER OUTPUT CONNECTORS - MOTOR 1		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.1		Id: 5/14










Sheet: /CONNECTORS M2/		
File: connectors_m2.kicad_sch		
Title: POWER OUTPUT CONNECTORS - MOTOR 2		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.1		Id: 8/14








Sheet: /CONNECTORS M3/ File: connectors_m3.kicad_sch		
Title: POWER OUTPUT CONNECTORS – MOTOR 3		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.1		Id: 11/14





Sheet: /CONNECTORS M4/		
File: connectors_m4.kicad_sch		
Title: POWER OUTPUT CONNECTORS - MOTOR 4		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.1		Id: 14/14