Transmission upgrade notes - personal

Transmission upgrade notes - personal

TRN upgrade / Gen1 (TNC-1X) notes - kept in my drawer, so sue me.

After an optical module swap on the old units (Gen1, 2019) the port can show UP with normal RX and cleared alarms but forward nothing. Seen 4x: TRN-042, TRN-051(B?deleted), Kemi, Ivalo side. Bounce the port. Do NOT swap the module again.

Newer boxes (Gen2/3 and the 7250 access switches) do not do this in my experience. Upgraded units: 2023-11 rollout to v6.1.4 made it much rarer.

Also: the Kemi transport room is behind the private road gate. The new police-code box has the padlock key. Previously Pekka had the key on his keyring. Ring Markku in service ops first if you do not know the site.

Transmission upgrade notes - personal

Transmission upgrade notes - personal

Gen1 box 2019-04-18 manufactured. Lab note: manually re-inserting the optical module did not clear the forwarding issue in 2/4 cases; a port bounce cleared it in 4/4. Possible supplier bug in the forwarding table update path.