

do not populate red components

populate blue components after SMT assembly